

Test Certificate



Tests Conducted By:

On Behalf Of: A N Other, 1 Any Street, Any Where, Any Time, Any PLace

Site: A N Other

Location: GARAGE

Asset: 001

Description: Jet Wash

Testcode: I017001022 Q121111111

Make:

Model:

Serial No:

Test	Result	Unit	Status
Visual			Pass
Insulation	>99.99	MOhm	Pass
Leakage	<0.1	mA	Pass
Load	<0.05	kVA	Information

Comments:

Overall Status: Pass

Date Of Test: 09/08/2006

Test Instrument: Seaward Europa Plus T37-0005

Tested By: M.GANCARZ

Signed By:

Test Certificate



Tests Conducted By:

On Behalf Of: A N Other, 1 Any Street, Any Where, Any Time, Any PLace

Site: A N Other

Location: GARAGE

Asset: 002

Description: Hand Buffer

Testcode: I017001022 Q121111111

Make:

Model:

Serial No:

Test	Result	Unit	Status
Visual			Pass
Insulation	>99.99	MOhm	Pass
Leakage	<0.1	mA	Pass
Load	<0.05	kVA	Information

Comments:

Overall Status: Pass

Date Of Test: 09/08/2006

Test Instrument: Seaward Europa Plus T37-0005

Tested By: M.GANCARZ

Signed By: